


Bottom Chord Bearing Cantilever T-Clip



Contact your RedBuilt Representative if cantilever exceeds $\frac{1}{3}$ of the truss span