


# Top Chord Bearing Cantilever Z-Clip



Contact your RedBuilt representative if cantilever exceeds  $\frac{1}{3}$  of the truss span